NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Committee

TECHNICAL BULLETIN — July 2014

378. Zierer Wave Swinger Service Bulletin

The committee has received the attached Service Bulletin from Zierer regarding modifications to their Wave Swinger device. The modification consists of the addition of a slack rope sensor and two secondary fixings for the hydraulic cylinders. This modification is a recommendation from the manufacturer.

The information contained within is that of the manufacturer and not NAFLIC. When following the advice from the manufacturer, you are reminded of your duties and responsibilities under HSG175 regarding modifications.



Karussell- und Spezialmaschinenbau GmbH

Head office:

Josef-Wallner-Straße 10 94469 Deggendorf

Factory Neuhausen:

Moosgasse 4 D-94560 Offenberg

Phone:

(+49) 991 9106 0 Switchboard (+49) 991 9106 38 Service

ax:

(+49) 991 9106 83 Service (+49) 991 9106 24 Engineering

E-Mail: <u>service@zierer.com</u>
Internet: <u>www.zierer.com</u>

Service Bulletin

Zierer Bulletin #	Revision:	Page	System	Description:	Date:	Issued:
SB-WS-1001	0	1 of 4	Wave Swinger	Service Bullitin	17.12.2012	wmt
Original Ride Manufacturer			Release Date	Affected Production Dates:	Ride Name:	
ZIERER – Karussell und Spezialmaschnenbau			02.02.2013	2011 and earlier	Wave Swinger	

1. Affected Serial Nos. and/or Ride Type:

ZIERER Karussell- und Spezialmaschinenbau GmbH Josef-Wallner-Str. 10, D-94469 Deggendorf

Serial 200 001 till 200 022 Serial 220 002 till 220 005

Serial 042 001 till 042 141 / 042 901 till 042 920

2. Reason for release:

With reference to EN 13814 and in collaboration with TUEV, we would like to inform you on the current additions to the components of the Zierer Wave Swinger that will be relevant for safe operation. We recommend to proceed with these modifications, in agreement with your local inspection authorities, also on your ride facility.

3. Actions to be taken:

3.1. Slack Rope Control at Lifting Rope





Slack Rope Control Zierer Article No.: VK080063


2 sets of slack rope controls, at the lifting rope, monitor and provide for a safe and tightened movement of the lifting rope. The controls are screwed next to the lifting ropes with mounting angles and fixing materials. They need to be subsequently integrated into the electronic control system. In the event of a malfunction, the rope will move away from the range of the sensor and cause a halt to the operation of the facility.

Zierer Bulletin #	Revision:	Page	System	Description:	Date:	Issued:
SB-WS-1001	0	1 of 4	Wave Swinger	Service Bullitin	17.12.2012	wmt



3.2. Hydraulic Cylinder - Safeguarding Guide Cross Top






<u>Lifting Cylinder-safeguarding [top] Zierer Article: HZ020078</u>
2 items of additional fork-safeguardings prevent the cylinder joint head from slipping away in the event of a breakage of the suspension. The fork-safeguardings are installed axially with a set of 4 screws each, and a distance of 138 mm to one another, at the guide cross.

Zierer Bulletin #	Revision:	Page	System	Description:	Date:	Issued:
SB-WS-1001	0	2 of 4	Wave Swinger	Service Bullitin	17.12.2012	wmt



3.3. Hydraulic Cylinder – Safeguarding Cylinder Clamping Bottom





<u>Lifting Cylinder-Safeguarding [bottom] Zierer Article: HZ020079</u>

1 item of additional counter-plate prevents the release of the cylinder clamping in the event of a breakage of the suspension. With this plate, the cylinder is additionally secured. The plate is bolted in the center with 2 screws to the cylinder eye.

Zierer Bulletin #	Revision:	Page	System	Description:	Date:	Issued:
SB-WS-1001	0	3 of 4	Wave Swinger	Service Bullitin	17.12.2012	wmt



4) Contact

For additional informations regarding installation, details and pricing of the mentioned modifications above, contact the:

ZIERER Karussell- und Spezialmaschinenbau GmbH

Moosgasse 4 D-94560 Offenberg

Mr. Martin Weinberger

Phone: (+49) 991 9106 55 Fax: (+49) 991 9106 83

E-Mail: <u>m.weinberger@zierer.com</u>

Internet: www.zierer.com

Zierer Bulletin #	Revision:	Page	System	Description:	Date:	Issued:
SB-WS-1001	0	4 of 4	Wave Swinger	Service Bullitin	17.12.2012	wmt