NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Committee

TECHNICAL BULLETIN - July 2014

371. Zierer Circular Letter - Tivoli Coasters

The committee has received the attached Circular Letter from Zierer following an incident.

Shear/trap hazards between open sided coaster cars and station platforms can occur on this and many other coaster types. Some examples of methods of reducing the risk are outlined in the Zierer letter.

The information contained within is that of the manufacturer and not NAFLIC. When following the advice from the manufacturer, you are reminded of your duties and responsibilities under HSG175 regarding modifications.

Committee Members: Mr. D Dadswell (Chairman), Mr. A Mellor (Secretary), Mr. P Smith, Mr. J Green, Mr. P Mitchell, Mr. D Cox, Mr. M Thirkettle, Mr. W Gilbert, Mr. H Fisher, Mr. J Shilling & Mr. D Inman

www.naflic.co.uk



Circular Letter Zierer – Tivoli Coaster / I-Track Coaster


Dear Customer,

We hereby inform you that one of our Tivoli Coasters has had an accident.

A passenger had stretched out his leg during a ride and injured himself in a collision with the station platform at the station entrance.

For this purpose, we would like to draw your attention to the information signs that need to be posted on your ride facility and warn the passengers not to extend body parts / limbs, such as arms or legs, out of the vehicles. We furthermore would like to recommend the following options to prevent accidents, should the warning signs be ignored.

Item [1.1] Boarding Parts






Item [1.2] Ramp at Platform



Item [1.3] Deflector Bars



Zierer Item No. BW090329: upholstered deflector bar

Best Regards

ZIERER Karussell- und Spezialmaschinenbau GmbH Martin Weinberger

Chibege M.