

Dartron

Issuing Entity:
Dartron Industries, Inc

P. O. Box 13114
Salem, Oregon 97309
Phone: 503-362-2341
Fax: 503-362-2536

www.dartronrides.com

Bulletin # SR-5K-0107-02

Release Date: 01/07/2007

Effective Date: 01/07/2007

Supersedes: N/A

Completion Date: 05/30/2007

Page 1 of 1

SERVICE BULLETIN

Ride Manufacturer: Dartron Industries, Inc.	Affected Production Dates: All Cliff Hanger Rides
Ride Name: Cliff Hanger	Affected Serial #'s All
Model # All	

Abstract of Issue: Dartron is aware of Cliff Hanger rides that have developed cracks in the bearing base. Dartron bulletin SB-5K-001 requires a visual inspection of the bearing base and Dartron bulletin PI-5K-003 communicates the procedures for repairing bearing base cracks and the installation of reinforcing plates.

Reason for release: Enough cracks have been discovered that Dartron has decided to make the installation of the reinforcing plates mandatory regardless of cracking in the bearing base.

Action to be taken: Dartron requires that all Cliff Hanger rides must have reinforcing plates installed on the bearing base before May 30, 2007. After 05/30/07 Cliff Hanger rides without reinforcing plates installed should not be allowed to operate.

Detail of issue:

1. Contact Dartron and arrange for shipment of the reinforcing plates.
2. Visually inspect for cracks as outlined in Dartron Service Bulletin SB-5K-001.
3. If cracks are discovered repair as described in Dartron Product Improvement Bulletin PI-5K-003.
4. If no cracks are discovered, install reinforcing plates as described in Dartron Product Improvement Bulletin PI-5K-003.