## **CARES Notification**

This document contains technical information provided by a CARES member agency. This document is FOR INFORMATION ONLY.

**Subject: Drive gear failure** 

Ride(s) affected: Fabbri Booster

**Date: August 17, 2011** 

Source: Leisure Technical Consultants Limited (LTC; http://www.ltci.co.uk/)

LTC has provided the following photograph of a drive gear (one of two) from a Fabbri Booster which failed during set-up. The photograph was supplied by a ride inspection body in the UK.

The manufacturer has been contacted, but as of this date has NOT issued a bulletin or official statement.

