NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Committee

TECHNICAL BULLETIN — October 2015

397. Huss service bulletin – Top Spin type rides

Huss has issued a service bulletin reporting cracking at the mounting points for the overhead restraints on Top Spin type rides. The cracks were detected during maintenance works on a similar ride to a Top Spin in the area of the shoulder restraint support. Related pictures are attached.

The manufacturer 'strongly recommends' the area in question be inspected by a certified inspection company.

The information contained within is that of the manufacturer and not NAFLIC. When following the advice from the manufacturer, you are reminded of your duties and responsibilities under HSG175 regarding modifications.



Address: HUSS Parts & Service GmbH Postfach 110206 D-28082 Bremen Head office:

Emil-Sommer-Straße 4-6, D-28329 Bremen Tel. 0421-49900-0 Fax 0421-49900-56 E-mail: service@hussparts.com Internet: http://www.hussrides.com

Your Ref.

Ext. -30

Date Jan 15, 2015

SERVICE LETTER No. 25-15

Ref.: Top Spin of serial number 69994

Dear Sirs,

According to our records you are the owner/operator of a HUSS **Top Spin** ride. If this is no longer the case, please return this letter to us together with the name, address and contact information of the current owner.

While maintenance works at a similar ride of the type Top Spin, cracks in the area of the shoulder restraint support have been detected.

Related pictures are attached.

To ensure the safety of your passengers, we strongly recommend to get the area in question inspected by a certified inspection company.

Feel free to contact us in case of questions or concerns.

Best regards,

André Warnecke

HUSS Parts & Service GmbH





