		Bulletin No:	B408R1214-0
R	CHANCE RIDES, INC.	Release Date:	September 10, 1999
S-MOIRT.	4219 Irving	Effective Date:	September 10, 1999
	Wichita, KS 67277-2328	Supersedes:	N/A
RIDES	U.S.A. Phone: 1-800-242-6231 • FAX: 1-316-942-7416		
	Website: www.rides.com	Completion Date	e: October 10, 1999
	E-mail: rides@rides.com	Page:	1 of 2

SERVICE BULLETIN

Ride Manufacturer: CHANCE RIDES, INC.

Affected Production Dates: 1/31/96 through 4/1/99

Affected Serial Nos.: 408-00196 through 408-04399

Ride Name: CHAOS

Model No.: 408

Abstract of Issue:

Sweep Insert Panel Rework

Reason For Release:

Chance Rides, Inc. has become aware that the sweep insert panels on the CHAOS amusement ride can wear at the guide pins. If the wear becomes severe, the panel can separate from the ride, causing possible damage to the ride or injury to the passengers and/or bystanders.

Action to be Taken:

All owners of the above noted amusement rides are required to order and install the Sweep Insert Modification Kit, part number K408R1214-0. The kit will be provided at a reduced cost if ordered within 30 days of the release date of this bulletin.

Install the kit using the instructions provided in this bulletin.

Kit number K408R1214-0 contains the following:

Part Number	<u>Component</u>	<u>Quantity</u>
K408R1214-003	GUIDE PIN WELDMENT	36
408-269-018	GUIDE PIN	36
60700600	HEX HEAD CAPSCREW (1/4-20 x 1-1/4")	36
60700800	HEX HEAD CAPSCREW (1/4-20 x 1-1/2")	36
68530200	FLAT WASHER (1/4")	72
68537000	LOCK WASHER (1/4")	36
64780800	LOCK NUT (1/4-20, Nylon Insert)	72

All work must be performed by qualified personnel, capable of understanding the function of the parts and their proper installation.

		Bulletin No: B408R1214-0
		Release Date: September 10, 1999
	4219 Irving	Effective Date: September 10, 1999
	Wichita, KS 67277-2328 U.S.A.	Supersedes: N/A
HANCE	D.S.A. Phone: 1-800-242-6231 • FAX: 1-316-942-741	8
RIDES	Website: www.rides.com	Completion Date: October 10, 1999
	E-mail: rides@rides.com	Page: 2 of 2
Ride Manufacturer: CHANC		Dates: 1/31/96 through 4/1/99
Ride Name: CHAOS	Affected Serial Nos.:	408-00196 through 408-04399
ModelNo.: 408		
Detail of Issue (continued):	NOTICE	
Use only those components aut	thorized, specified or provided by Chance Rides,	Inc.
• -		
	ALLY DISCLAIMS ANY LIABILITY for losses as	
and/or modifications or additi	ons and installations of unauthorized component	ts.
INSTALLATION INST	RUCTIONS	
	pins and grind smooth (4 places each insert	panel).
0 I	guide pins at the narrow end of the insert pan	el and the guide weldments as shown
	places each insert panel).	or and the guide worallion to us one with
	-	ashers and look washers. Install the
3. Install guide pins with	$1/4-20 \ge 1-1/2$ " hex head capscrews, flat w 1/4-20 $\ge 1-1/4$ " hex head capscrews, flat	t washers and lock washers. Install the
capscrews from the ins		
1		including the rivers which secure the
IMPORTANT: Inspect al molded pa	l components of the sweep insert panels, i anel to the frame. Replace any worn or dama	aged parts before installing the sweep
	els on the ride.	
		Guide weldment
Guide pin	1 - N	
•		o
		7
- 		
<i>⊢5.31<u>"</u> </i>		
	42.75"	