



NUMBER: B400R1055-0

DATE: Feb. 1, 1990

SUPERSEDES:

SERVICE BULLETIN

Effective Serial Numbers: All Units

Ride: GIANT GONDOLA WHEEL

Subject: PLATING ON GONDOLA STEM

It has come to the attention of Chance Rides, Inc. that there were some problems that developed during the plating process of the gondola stems. The result of this plating problem is external rusting and cosmetic only. It does not affect the integrity of the ride.

It does, however, cause a rusting discoloration of the gondola stem.

All GIANT GONDOLA WHEEL ride owners should inspect the stems for this rusting discoloration. If the problem exists, new stems may be ordered. When the original gondola stems have been returned to Chance Rides, Inc. full credit will be issued. Stems must be ordered within one year from the date of this bulletin to receive credit.

When ordering gondola stems, order part number 377-8262500.

All work must be performed by qualified personnel, capable of understanding the function of the parts and their proper installation.

NOTICE

Use only those components authorized, specified or provided by the manufacturer. If any alterations and/or modifications or additions and installations of unauthorized components are made to the original design without the manufacturer's explicit written consent or without direct supervision by a manufacturer's representative, Chance Rides, Inc. makes no claim as to the integrity of the altered or modified ride.

If there are any questions regarding this inspection contact the Chance Rides Customer Service Department.

