

# *Majestic Manufacturing, Inc.*

Majestic Manufacturing, Inc. \* PO Box 128  
4536 State Route 7, New Waterford, Ohio 44445

Subject: Rectifier Power Setting  
Floor Pick-up

## **ATTN: OWNER/OPERATOR**

This bulletin pertains to the operation of your Majestic unit. This Service Bulletin must remain with the owner's manual at all times. If you have any questions regarding the Bulletin, contact our office at 330/457-2447, M-F 8:00a.m. -4:30p.m. E.S.T. \*\* Fax 330/457-7490.

## **SERVICE BULLETIN**

Date: September 16, 1993

S.B. Number: 93-1

### Notice:

### **FLOOR PICK-UP UNITS**

Majestic Manufacturing is advising all owners of a Majestic D.C. Power Supply Rectifier to monitor the following:

All rectifiers should be monitored so they do not exceed 36 volts D.C. during normal operation.

We advise that the voltage be monitored not to exceed 36 volts D.C. at any time. Failure to operate the rectifier at factory specification can result in excessive speed of the bumper cars and the possibility for a risk of injury to the driver or passenger of the bumper car.

If you have any questions on factory standards or procedures on our equipment, contact Majestic Manufacturing, Inc. during normal business hours of 8:00 a.m. to 4:30 p.m. Monday through Friday, E.S.T. at 330/457-2447 or toll free at 1-888-MAJ-RIDE.

Revised 01/06/03