



NUMBER: A406R1143-0

DATE: OCT. 22, 1993

SUPERSEDES:

SAFETY ALERT

Effective Serial Number: All Units

Ride: CENTURY WHEEL

Subject: Sweep and Spreader Lighting

Chance Rides, Inc. has become aware of at least one case in which all of the bases of the sweep lights enclosed by one light cover on the CENTURY WHEEL amusement ride broke. When this occurred, the section fell from the ride.

Chance Rides, Inc. requires all owner/operators of the above noted amusement rides to follow the rework safety precautions in this Safety Alert Bulletin. Failure to follow the rework instructions outlined in this bulletin prior to the operation of the ride can result in injury to patrons and/or employees.

All work must be performed by qualified personnel, capable of understanding the function of the parts and their proper installation.

NOTICE

Use only those components authorized, specified or provided by Chance Rides, Inc.

Chance Rides, Inc. SPECIFICALLY DISCLAIMS ANY LIABILITY for losses associated with any unauthorized alterations and/or modifications or additions and installations of unauthorized components.

Rework Instructions

1. Remove the #10 x 2-1/4 long machine screw in the light covers located on each sweep.
2. Using 3/16 black tie wraps, secure the light covers to the sweeps. Insert one tie wrap through the holes where the machine screws were removed and fasten around the sweep. Secure each light cover at two locations. NOTE: If cover only contains one hole, drill a second hole at the opposite end of cover for the second tie wrap.
3. Perform the above steps on all spreader bar light covers as well as all sweep light covers.

