



NUMBER: B392R1066-0

DATE: May 22, 1990

SUPERSEDES:

SERVICE BULLETIN

Effective Serial Number: All Units - Chance Rides, Inc.
All Units - Chance Manufacturing Co., Inc.

Chance Rides, Inc. SPECIFICALLY DISCLAIMS ANY
LIABILITY for losses associated with rides
produced by Chance Manufacturing Company, Inc.

Ride: THUNDERBOLT

Subject: Sweep Bars

Chance Rides, Inc. requires all owners of THUNDERBOLT amusement rides to inspect the ears on the sweeps and on the double sweeps for cracks as shown in the illustration on this bulletin. If the ears crack, failure of the part could occur, resulting in injury to passengers.

If any cracks are found, do not attempt to repair, contact Chance Rides Customer Service Department immediately for replacement parts. Do not operate ride until the Chance Rides, Inc. approved repair has been complete.

All work must be performed by qualified personnel, capable of understanding the function of the parts and their proper installation.

NOTICE

Use only those components authorized, specified or provided by Chance Rides, Inc.

Chance Rides, Inc. SPECIFICALLY DISCLAIMS ANY LIABILITY for losses associated with any unauthorized alterations and/or modifications or additions and installations of unauthorized components.

