



COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF AGRICULTURE
BUREAU OF RIDE & MEASUREMENT STANDARDS
AMUSEMENT RIDE SAFETY DIVISION

TO: Owners and inspectors on Moser Spring ride AKA Freefall

FROM: Joseph G. Filoromo, supervisor

SUBJECT: Inspection Alert

DATE: July 12, 2011

An incident has occurred on one of the above mentioned ride type where the top pulley became detached form the cylinder causing the ride to drop. In this incident, the shock absorbing devices were able to prevent disastrous injuries.

To prevent this from happening please be reminded of the required inspection point that is outlined on page 21 of the manual (attached)

THANK YOU




[E-mail: jfiloromo@state.pa.us](mailto:jfiloromo@state.pa.us)

SPRING RIDE

CONTROLLI - CHECKS

CONTROLLI SETTIMANALI WEEKLY CHECKS



Verificare il grano blocca lo stelo del cilindro di sollevamento al supporto pulegge.

Check the screw spring that blocks the lifting cylinder to the pulley support.

MOSER RIDES SRL

VIA ABETONE BRENNERO, 46035 OSTIGLIA, Mantova, ITALY

PH +39 0386 800001 - FAX +39 0386 802099

EMAIL Moser@MoserRides.com