## **NAFLIC**


National Association For Leisure Industry Certification

Standards & Related Documents Committee

TECHNICAL BULLETIN — October 2015

## 399. Nottingham UK Miami Trip defect

A defect has been identified on a Nottingham UK Miami Trip of around 10 years old. A crack has formed at the weld between the bearing housing and the hydraulic motor mounting plate. This is believed to be a 'one off' incident and it is understood that the ride's use may be heavier than the normal use expected for this type of device. Operators and IBs are reminded to inspect this area carefully.



Committee Members: Mr. D Dadswell (Chairman), Mr. A Mellor (Secretary), Mr. P Smith, Mr. J Green, Mr. D Cox, Mr. M Thirkettle, Mr. I Davies, Mr. J Shilling & Mr. D Inman