

459.

Zamperla Rockin' Tug axle cracking

A UK registered inspection body has reported defects on a Zamperla Rockin' Tug. During the annual inspection both the main gondola axles were removed from the device and subjected to magnetic particle inspection. Both axles were found to be cracked and were replaced with new items. The device in question is approximately 10-years-old.



Committee Members: Mr. D Dadswell (Chairman), Mr. A Mellor (Secretary), Mr. P Smith, Mr. J Green,
Mr. D Cox, Mr. I Davies, Mr. J Shilling, Mr. D Inman & Mr. R Hiscoe

www.naffic.co.uk

Supported By:

