

## 521.

# Non-ADIPS registered 3rd party inspections

NAFLIC has been informed of a possible clash of or gap in responsibility regarding inspections of some areas of a device.

Occasionally, on instruction from the device controller and NOT under instruction from the AIB, a 3rd party IB will inspect part of an amusement device (such as pneumatics, hydraulics, chains, lifting devices (LOLER)). While the 3rd party IB is not acting under the AIB, there is a possibility to issue a DOC on a device that has outstanding inspections or defects that have been found by the 3rd party IB, should the reports not be available or checked.

It is the AIB's responsibility to check these 3rd. party inspections are done and to check the reports if something affects the ride, i.e. air receivers.

*The information contained within is provided in good faith and every effort has been made to ensure its accuracy. NAFLIC shall not be held responsible for any loss of business or profits, nor any direct or indirect or consequential loss or damage resulting from the publication/distribution and/or use of the information provided or any inaccuracy herein.*