



NUMBER: B400R1047-0

DATE: July 17, 1989

SUPERSEDES:

SERVICE BULLETIN

Effective Serial Number: All Units

Ride: GIANT GONDOLA WHEEL
(Portable Model Only)

Subject: Trailer Leveling Instructions

Running a ride which is not properly leveled can cause stress on mechanical parts, reducing the service life of these parts. Damage can also occur to the gondolas, resulting in personal injury to passengers and/or bystanders.

The trailers for the portable model GIANT GONDOLA WHEEL are equipped with hydraulic cylinders and screw jacks for leveling the ride. Operation of these devices and proper blocking procedures are outlined in the CHANCE OPERATION AND MAINTENANCE MANUAL.

If soft ground conditions permit settling of the ride, or if the ride is improperly blocked or leveled, clearance can be reduced between the gondolas and the floors in the passenger loading areas.

Other evidence that the ride is not level is the position of the drive tires on the rim irons. Drive tires which are rubbing or are out of alignment are an indication that the trailers are not properly leveled.

DO NOT OPERATE A RIDE WHICH IS NOT PROPERLY BLOCKED OR THAT SHOWS EVIDENCE OF IMPROPER LEVELING. Reblocking and releveling the ride, as described in the CHANCE OPERATION AND MAINTENANCE MANUAL, is necessary before operation of the ride can resume.

All work must be performed by qualified personnel, capable of understanding the function of the parts and their proper installation. If there are any questions regarding the instructions or this rework, contact the CHANCE CUSTOMER SERVICE DEPARTMENT.